


# Curved Manifold Assembly

## Designed for Easy Installation

In order to provide the option of installing a manifold monitoring assembly in the neck of a manhole, System Studies supplies a double Manifold Monitoring Assembly with a curved bracket (Part No. 9802-3062-MBV-2).

This curved Manifold Monitoring Assembly contains all of the components of our 9800-3062-MBV-2 assembly, except that the mounting bracket is curved to conform to the circumference of a standard 36-inch diameter manhole collar. The 9802-3062-MBV-2 model has two Flow Finder Manifolds equipped with nickel-plated brass check valves and 3/8" brass conductor tubing fittings in each port. It is monitored by a High Resolution Dual Transducer.

Have any questions about the Curved Manifold Assembly's performance capabilities, installation



**Part No. 9802-3062-MBV-2**

## System Studies Incorporated



2-1340 East Cliff Drive  
Santa Cruz, CA 95062  
(831) 475-5777  
(800) 247-8255  
(831) 475-9207 FAX  
[www.airtalk.com](http://www.airtalk.com)