

System Studies Incorporated



2-1340 East Cliff Drive
 Santa Cruz, CA 95062
 (831) 475-5777
 (800) 247-8255
 (831) 475-9207 FAX
 www.airtalk.com

Pressure Transducer Conversion Chart (CPA/30)			
Pressure in PSI	Current in mA	Pressure in PSI	Current in mA
0.00	6.00	16.00	13.46
1.00	6.47	17.00	13.92
2.00	6.93	18.00	14.39
3.00	7.40	19.00	14.85
4.00	7.86	20.00	15.32
5.00	8.33	21.00	15.79
6.00	8.80	22.00	16.25
7.00	9.26	23.00	16.72
8.00	9.73	24.00	17.18
9.00	10.19	25.00	17.65
10.00	10.66	26.00	18.12
11.00	11.13	27.00	18.58
12.00	11.59	28.00	19.05
13.00	12.06	29.00	19.51
14.00	12.52	30.00	19.98
15.00	12.99		